

HighFinesse  
The Standard of Accuracy

HighFinesse Tutorial

# Setting up the HighFinesse LWA-10k and LWA-100k

## How to ...

... set up the HighFinesse LWA-10k  
and LWA-100k

This tutorial does not replace reading the linewidth analyzer (LWA) user manual.





Make sure that your laser input fulfills the following requirements:

- a) The laser must be cw.
- b) The laser must not be scanned during the measurement.
- c) Provide 0.5 to 10 mW in a PM Fiber with FC/APC connector.  
Ideally provide 5 to 10 mW for the best performance of the instrument.
- d) The laser must not exceed the maximum linewidth specified for the  
LWA-10k - 30 MHz @ 100 ms and LWA-100k - 100 MHz @ 100 ms.
- e) In case the laser is sensitive to back reflection the use of an isolator  
with 55 dB between laser and LWA is recommended.

LWA products brochure

<https://www.highfinesse.com/en/linewidthanalyzer/linewidthanalyzer-further-information/product-brochure-linewidthanalyzer.pdf>



 bin	24.08.2022 09:38	Dateiordner
 drivers	24.08.2022 09:38	Dateiordner
 Control Measurement.pdf	04.07.2022 10:08	PDF Document
 Iwa_install.exe	04.07.2022 17:25	Anwendung




2

A red speech bubble with a white outline and a tail pointing towards the bottom left. Inside the bubble, the text "Open ..." is written in white.


lwa\_install.exe  
Type: Application

- Windows 10, 64 bit or higher
- Intel® Core™ i5 equivalent or better
- Memory 16 GB or better
- At least 1 Ethernet and  
1 USB 3.0 Port





- 3a Connect the analyzer via Ethernet to the same network as the computer running the Software.
- 3b Connect the digitizer via USB to the same computer running the software.
- 3c Connect the analyzer output to the digitizer input using the BNC cable (with T-adapter with 50 Ohm termination at the digitizer).
- 3d Connect the laser via an SM fiber with FC/APC connector.





In case you would like to **directly connect** the instrument to the computer using an **Ethernet cable** make sure the **TCP/IP** protocol of the **network adapter** is set to **automatic**.



5



Wait for the LWA to adapt to the **laser**. This can take up to 10 minutes but **typically takes 30 seconds**.




6





If “**Failed**” is displayed or “**Stabilizing**” for more than 20 minutes refer to the troubleshooting section in the manual.



7



8





In the “**Time Series**” window the **fundamental data measured** is displayed by the instrument: The frequency deviations are **displayed as a function of time**.

The **indicator 8** shows the standard deviation of the observed frequency deviations. This should not be mistaken by the linewidth.



9



Adjust the Resolution [Hz]/measurement time.



10 Hz corresponds to the maximum measurement time of 100 ms.

This will both affect the measurement time and resolution in the frequency noise density spectrum.







11



In the “**Lineshape**” window the **laser lineshape** is displayed.


The fullwidth half maximum is displayed assuming a pure **11a** Gaussian or **11b** Cauchy/Lorentzian lineshape.





Click to “File – Export” to export data as .csv or .npz.

For post analysis in Python see examples for the software installation path.



# HighFinesse

The Standard of Accuracy



HighFinesse GmbH  
Neckarsulmer Straße 5  
72072 Tübingen, Germany



+ 49 (0) 7071 - 53 918 0  
[info@highfinesse.com](mailto:info@highfinesse.com)  
[www.highfinesse.com](http://www.highfinesse.com)



Find further information on  
products, data sheets and  
distributors on our website